



## Chapter Outline

- 1. Introduction
- 2. The Turning Process
- 3. Lathes and Lathe Operations
- 4. **Boring and Boring Machines**
- 5. Drilling, Drills, and Drilling Machines
- 6. Reaming and Reamers
- 7. Tapping and Taps


- Machining processes has the capability of producing parts that are round in shape
- Such as miniature screws for the hinges of eyeglass frames and turbine shafts for hydroelectric power plants
- Most basic machining processes is turning where part is rotated while it is being machined
- Turning processes are carried out on a *lathe* or by similar *machine tools*
- Highly versatile and produce a wide variety of shapes







- Turning is performed at various:
- Rotational speeds, N, of the workpiece clamped in a spindle
- Depths of cut, d
- Feeds, *f*, depending on the workpiece materials, cuttingtool materials, surface finish, dimensional accuracy and characteristics of the machine tool



- Majority of turning operations use simple single-point cutting tools, which is a right-hand cutting tool
- Important process parameters have a direct influence on machining processes and optimized productivity

#### **Tool Geometry**


- Rake angle control both the direction of chip flow and the strength of the tool tip
- Side rake angle controls the direction of chip flow
- Cutting-edge angle affects chip formation, tool strength and cutting forces

#### **Tool Geometry**

- Relief angle controls interference and rubbing at the tool—workpiece interface
- Nose radius affects surface finish and tool-tip strength

|                               | High-speed steel |              |               |                | Carbide inserts           |              |              |               |                |                           |
|-------------------------------|------------------|--------------|---------------|----------------|---------------------------|--------------|--------------|---------------|----------------|---------------------------|
| Material                      | Back<br>rake     | Side<br>rake | End<br>relief | Side<br>relief | Side and end cutting edge | Back<br>rake | Side<br>rake | End<br>relief | Side<br>relief | Side and end cutting edge |
| Aluminum and magnesium alloys | 20               | 15           | 12            | 10             | 5                         | 0            | 5            | 5             | 5              | 15                        |
| Copper alloys                 | 5                | 10           | 8             | 8              | 5                         | 0            | 5            | 5             | 5              | 15                        |
| Steels                        | 10               | 12           | 5             | 5              | 15                        | -5           | -5           | 5             | 5              | 15                        |
| Stainless steels              | 5                | 8-10         | 5             | 5              | 15                        | -5-0         | -5-5         | 5             | 5              | 15                        |
| High-temperature alloys       | 0                | 10           | 5             | 5              | 15                        | 5            | 0            | 5             | 5              | 45                        |
| Refractory alloys             | 0                | 20           | 5             | 5              | 5                         | 0            | 0            | 5             | 5              | 15                        |
| Titanium alloys               | 0                | 5            | 5             | 5              | 15                        | -5           | -5           | 5             | 5              | 5                         |
| Cast irons                    | 5                | 10           | 5             | 5              | 15                        | -5           | -5           | 5             | 5              | 15                        |
| Thermoplastics                | 0                | 0            | 20-30         | 15-20          | 10                        | 0            | 0            | 20-30         | 15-20          | 10                        |
| Thermosets                    | 0                | 0            | 20-30         | 15 - 20        | 10                        | 0            | 15           | 5             | 5              | 15                        |

#### **Tool Geometry**



#### **Material-removal Rate**

The material-removal rate (MRR) is the volume of material removed per unit time (mm³/min)

#### **Material-removal Rate**

- The average diameter of the ring is  $D_{avg} = \frac{D_0 + D_f}{2}$
- Since there are N revolutions per minute, the removal rate is

$$MMR = \pi D_{avg} dfN$$
 or reduce to  $MMR = dfV$ 


Since the distance traveled is I mm, the cutting time is

$$t = \frac{l}{fN}$$

The cutting time does not include the time required for tool approach and retraction

#### **Forces in Turning**

- The 3 principal forces acting on a cutting tool are important in the design of machine tools, deflection of tools and workpieces for precision-machining operations
- Cutting force acts downward on the tool tip and deflect the tool downward and the workpiece upward
- Thrust force (or feed force) acts in the longitudinal direction




#### **Roughing and Finishing Cuts**

- First practice is to have one or more roughing cuts at high feed rates and large depths of cut
- Little consideration for dimensional tolerance and surface roughness
- Followed by a finishing cut, at a lower feed and depth of cut for good surface finish

#### **Tool Materials, Feeds, and Cutting Speeds**

The range of applicable cutting speeds and feeds for a variety of tool materials is shown



#### **EXAMPLE 23.1**

#### **Material-removal Rate and Cutting Force in Turning**

A 150-mm-long, 12.5-mm-diameter 304 stainless steel rod is being reduced in diameter to 12.0 mm by turning on a lathe. The spindle rotates at *N* 400 rpm, and the tool is travelling at an axial speed of 200 mm/min. Calculate the cutting speed, material-removal rate, and cutting time.

#### Solution

#### **Material-removal Rate and Cutting Force in Turning**

The maximum cutting speed is

$$V = \pi D_0 N = \frac{\pi (12.5)(400)}{1000} = 15.7 \text{ m/min}$$

The cutting speed at the machined diameter is

$$V = \pi D_0 N = \frac{\pi (12.0)(400)}{1000} = 15.1 \text{ m/min}$$

The depth of cut is 
$$d = \frac{12.5 - 12.0}{2} = 0.25 \text{ mm}$$

#### Solution

#### **Material-removal Rate and Cutting Force in Turning**

The feed is 
$$f = \frac{200}{400} = 0.5 \text{ mm/rev}$$

The material-removal rate is

$$MMR = (\pi)(12.25)(0.25)(0.5)(400) = 1924 \text{ mm}^3/\text{min} = 2 \times 10^{-6} \text{ m}^3/\text{min}$$

The actual time to cut is

$$t = \frac{150}{(0.5)(400)} = 0.75 \,\mathrm{mm}$$

# Lathes and Lathe Operations

- Lathes are considered to be the oldest machine tools
- Speeds may range from moderate to high speed machining
- Simple and versatile
- But requires a skilled machinist
- Lathes are inefficient for repetitive operations and for large production runs



# Lathes and Lathe Operations: Lathe Components


#### **Lathe Specifications**

- Max diameter of the workpiece that can be machined
- Max distance between the headstock and tailstock centers
- 3. Length of the bed

| Machine tool                           | Maximum<br>dimension (m) | Power (kW) | Maximum<br>speed (rpm) |
|----------------------------------------|--------------------------|------------|------------------------|
| Lathes (swing/length)                  |                          |            |                        |
| Bench                                  | 0.3/1                    | <1         | 3000                   |
| Engine                                 | 3/5                      | 70         | 4000                   |
| Turret                                 | 0.5/1.5                  | 60         | 3000                   |
| Automatic screw machines               | 0.1/0.3                  | 20         | 10,000                 |
| Boring machines (work diameter/length) |                          |            |                        |
| Vertical spindle                       | 4/3                      | 200        | 300                    |
| Horizontal spindle                     | 1.5/2                    | 70         | 1000                   |
| Drilling machines                      | -                        |            |                        |
| Bench and column (drill diameter)      | 0.1                      | 10         | 12,000                 |
| Radial (column to spindle distance)    | 3                        | _          | _                      |
| Numerical control (table travel)       | 4                        | _          | _                      |

Note: Larger capacities are available for special applications.


# Lathes and Lathe Operations: Workholding Devices and Accessories



### Lathes and Lathe Operations: Types of Lathes

#### **Turret Lathes**


 Perform multiple cutting operations, such as turning, boring, drilling, thread cutting, and facing



### Lathes and Lathe Operations: Types of Lathes


#### **Computer-controlled Lathes**

Movement and control of the machine tool and its components can be achieved




## **Boring and Boring Machines**

- The cutting tools are mounted on a boring bar to reach the full length of the bore
- Boring bars have been designed and built with capabilities for damping vibration
- Large workpieces are machined on boring mills



## **Boring and Boring Machines**

- In horizontal boring machines, the workpiece is mounted on a table that can move horizontally in both the axial and radial directions
- A vertical boring mill is similar to a lathe, has a vertical axis of workpiece rotation



### **Boring and Boring Machines**


#### **Design Considerations for Boring:**

- 1. Through holes should be specified
- 2. Greater the length-to-bore-diameter ratio, the more difficult it is to hold dimensions
- Interrupted internal surfaces should be avoided

- Holes are used for assembly with fasteners, for design purposes or for appearance
- Hole making is the most important operations in manufacturing
- Drilling is a major and common hole-making process



 Drills have high length-to-diameter ratios, capable of producing deep holes



- Drills are flexible and should be used with care in order to drill holes accurately and to prevent breakage
- Drills leave a burr on the bottom surface upon breakthrough, necessitating deburring operations

| General Capabilities of Drilling and Boring Operations |                     |                     |         |  |
|--------------------------------------------------------|---------------------|---------------------|---------|--|
|                                                        |                     | Hole depth/diameter |         |  |
| Cutting tool                                           | Diameter range (mm) | Typical             | Maximum |  |
| Twist drill                                            | 0.5-150             | 8                   | 50      |  |
| Spade drill                                            | 25-150              | 30                  | 100     |  |
| Gun drill                                              | 2-50                | 100                 | 300     |  |
| Trepanning tool                                        | 40-250              | 10                  | 100     |  |
| Boring tool                                            | 3-1200              | 5                   | 8       |  |


#### **Twist Drill**


- The most common drill is the conventional standardpoint twist drill
- The geometry of the drill point is such that the normal rake angle and velocity of the cutting edge vary with the distance from the center of the drill
- Main features of this drill are:
- Point angle
- Lip-relief angle
- 3. Chiseledge angle
- 4. Helix angle

#### Twist Drill

- Drills are available with a chip-breaker feature ground along the cutting edges
- Other drill-point geometries have been developed to improve drill performance and increase the penetration rate

#### **Other Types of Drills**





# Drilling, Drills, and Drilling Machines: Material-removal Rate in Drilling

The material-removal rate (MRR) in drilling is the volume of material removed per unit time

$$MMR = \left(\frac{\pi D^2}{4}\right) fN$$

# Drilling, Drills, and Drilling Machines: Thrust Force and Torque

#### **EXAMPLE 23.4**

#### Material-removal Rate and Torque in Drilling

A hole is being drilled in a block of magnesium alloy with a 10-mm drill bit at a feed of 0.2 mm/rev and with the spindle running at N = 800 rpm. Calculate the material-removal rate.

# Drilling, Drills, and Drilling Machines: Thrust Force and Torque

#### Solution

#### **Material-removal Rate and Torque in Drilling**

The material-removal rate is

$$MMR = \left(\frac{\pi (10)^2}{4}\right)(0.2)(800) = 12,570 \text{ mm}^3 / \text{min} = 210 \text{ mm}^3 / \text{s}$$

# Drilling, Drills, and Drilling Machines: Drill Materials and Sizes

- Drills are made of high-speed steels and solid carbides or with carbide tips
- Drills are coated with titanium nitride or titanium carbon nitride for increased wear resistance

#### **Drilling Recommendations**

The speed is the surface speed of the drill at its periphery

| General Recommendation | s for Speeds | and Feeds in Drilli | ing |
|------------------------|--------------|---------------------|-----|
|------------------------|--------------|---------------------|-----|

|                    |               | Drill diameter |         |             |           |  |
|--------------------|---------------|----------------|---------|-------------|-----------|--|
|                    |               | Feed, n        | nm/rev  | Speed, rpm  |           |  |
|                    | Surface speed | 1.5 mm         | 12.5 mm | 1.5 mm      | 12.5 mm   |  |
| Workpiece material | m/min         |                |         |             |           |  |
| Aluminum alloys    | 30-120        | 0.025          | 0.30    | 6400-25,000 | 800-3000  |  |
| Magnesium alloys   | 45-120        | 0.025          | 0.30    | 9600-25,000 | 1100-3000 |  |
| Copper alloys      | 15-60         | 0.025          | 0.25    | 3200-12,000 | 400-1500  |  |
| Steels             | 20-30         | 0.025          | 0.30    | 4300-6400   | 500-800   |  |
| Stainless steels   | 10-20         | 0.025          | 0.18    | 2100-4300   | 250-500   |  |
| Titanium alloys    | 6-20          | 0.010          | 0.15    | 1300-4300   | 150-500   |  |
| Cast irons         | 20-60         | 0.025          | 0.30    | 4300-12,000 | 500-1500  |  |
| Thermoplastics     | 30-60         | 0.025          | 0.13    | 6400-12,000 | 800-1500  |  |
| Thermosets         | 20-60         | 0.025          | 0.10    | 4300–12,000 | 500-1500  |  |

Note: As hole depth increases, speeds and feeds should be reduced. The selection of speeds and feeds also depends on the specific surface finish required.

#### **Drilling Recommendations**

- The feed in drilling is the distance the drill travels into the workpiece per revolution
- Chip removal during drilling can be difficult for deep holes in soft and ductile workpiece materials

| General Troubleshooting Guide for Drilling Operations |                                                                                                                                   |  |  |
|-------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|--|--|
| Problem                                               | Probable causes                                                                                                                   |  |  |
| Drill breakage                                        | Dull drill, drill seizing in hole because of chips clogging flutes,                                                               |  |  |
|                                                       | feed too high, lip relief angle too small                                                                                         |  |  |
| Excessive drill wear                                  | Cutting speed too high, ineffective cutting fluid, rake angle too                                                                 |  |  |
|                                                       | high, drill burned and strength lost when drill was sharpened                                                                     |  |  |
| Tapered hole                                          | Drill misaligned or bent, lips not equal, web not central                                                                         |  |  |
| Oversize hole                                         | Same as previous entry, machine spindle loose, chisel edge not                                                                    |  |  |
|                                                       | central, side force on workpiece                                                                                                  |  |  |
| Poor hole surface finish                              | Dull drill, ineffective cutting fluid, welding of workpiece material on drill margin, improperly ground drill, improper alignment |  |  |


#### **Drill Reconditioning**

- Drills are reconditioned by grinding them either manually or with special fixtures
- Hand grinding is difficult and requires considerable skill in order to produce symmetric cutting edges
- Grinding on fixtures is accurate and is done on special computer controlled grinders


#### **Measuring Drill Life**

- Drill life is measured by the number of holes drilled before they become dull and need to be re-worked or replaced
- Drill life is defined as the number of holes drilled until this transition begins

- Drilling machines are used for drilling holes, tapping, reaming and small-diameter boring operations
- The most common machine is the drill press





- The types of drilling machines range from simple bench type drills to large radial drills
- The drill head of universal drilling machines can be swiveled to drill holes at an angle
- Numerically controlled three-axis drilling machines are automate in the desired sequence using turret
- Drilling machines with multiple spindles (gang drilling) are used for high-production-rate operations



## Reaming and Reamers


- Reaming is an operation used to:
- Make existing hole dimensionally more accurate
- Improve surface finish
- Most accurate holes in workpieces are produced by:
- Centering
- 2. Drilling
- 3. Boring
- 4. Reaming





# Tapping and Taps

- Internal threads in workpieces can be produced by tapping
- A tap is a chip-producing threading tool with multiple cutting teeth
- Tapered taps are designed to reduce the torque required for the tapping of through holes
- Bottoming taps are for tapping blind holes to their full depth
- Collapsible taps are used in large-diameter holes





# Tapping and Taps

- Tapping may be done by hand or with machines:
- Drilling machines
- 2. Lathes
- Automatic screw machines
- 4. Vertical CNC milling machines
- One system for the automatic tapping of nuts is shown

